

HAER
CAL
14-BISHV,
2C-

**HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS**

**Bishop Creek Hydroelectric System, Control Station
Worker Cottage (Building 103)
Bishop Creek
Bishop Vicinity
Inyo County
California**

HAER No. CA-145-1-C

Gregory L. O'Loughlin, photographer

June, 1995

- CA-145-1-C-1 EXTERIOR OVERVIEW SHOWING FRONT (EAST) END AND SOUTH SIDE OF BUILDING 103, ROCK WALL AND MATURE COTTONWOOD TREES IN FOREGROUND, CONTROL SUBSTATION BEHIND BUILDING 103, AND BUILDING 106 BEHIND THE COTTONWOOD TREE IN THE NORTH BACKGROUND. VIEW TO NORTH.
- CA-145-1-C-2 EXTERIOR OVERVIEW SHOWING FRONT (EAST) END AND NORTH SIDE OF BUILDING 103. CONTROL SUBSTATION IS BEHIND BUILDING 103 AND BUILDING 102 IS VISIBLE IN THE LEFT BACKGROUND OF PHOTO. VIEW TO SOUTHWEST.
- CA-145-1-C-3 EXTERIOR OF SOUTH SIDE SHOWING DOOR TO ENCLOSED FRONT PORCH ON PHOTO RIGHT AND DOOR TO KITCHEN AT PHOTO LEFT. VIEW TO NORTH.
- CA-145-1-C-4 EXTERIOR OF SOUTH SIDE AND WEST END SHOWING DOOR TO KITCHEN AT PHOTO CENTER STAIRWAY ENTRY TO BASEMENT AT LEFT OF KITCHEN DOOR. VIEW TO NORTHEAST.
- CA-145-1-C-5 EXTERIOR OF WEST END SHOWING ENCLOSED REAR PORCH ABOVE SUPPORTS FOR REAR PORTION OF BASEMENT. NORTH SIDE ENTRANCE TO BASEMENT IS VISIBLE AT LEFT PHOTO CENTER. VIEW TO SOUTHEAST.
- CA-145-1-C-6 INTERIOR VIEW OF NORTH ENTRANCE TO BASEMENT SHOWING WORKBENCH AT PHOTO LEFT AND ONE OF TWO DOORWAYS TO MAIN BASEMENT AREA AT PHOTO RIGHT. VIEW TO NORTH.

BISHOP CREEK HYDROELECTRIC SYSTEM,
CONTROL STATION,
WORKER COTTAGE (BUILDING 103)
HAER No. CA-145-1-C
INDEX TO PHOTOGRAPHS (Page 2)

- CA-145-1-C-7 INTERIOR VIEW OPPOSITE CA-145-1-C-6 SHOWING STAIRS TO SOUTH SIDE BASEMENT ENTRANCE AND BOTH DOORS TO MAIN BASEMENT AREA. VIEW TO SOUTH.
- CA-145-1-C-8 DETAIL OF ROCK RETAINING WALL ON SOUTH INTERIOR SIDE OF REAR PORTION OF BASEMENT ADJACENT TO STAIRS TO SOUTH SIDE BASEMENT ENTRANCE. VIEW TO SOUTHWEST.
- CA-145-1-C-9 INTERIOR OF MAIN BASEMENT AREA LOOKING THROUGH SOUTH SIDE DOOR TO MAIN BASEMENT AREA. VIEW TO EAST.
- CA-145-1-C-10 INTERIOR OF MAIN BASEMENT AREA SHOWING WORKBENCH ALONG NORTH WALL BELOW TWO OF THE THREE 1-LIGHT, SIDE-HINGED WINDOWS ON THIS WALL. VIEW TO NORTHEAST.
- CA-145-1-C-11 INTERIOR OF MAIN BASEMENT AREA, SOUTHEAST CORNER OF HOUSE. VIEW TO SOUTHEAST.
- CA-145-1-C-12 INTERIOR OF MAIN BASEMENT AREA, NORTH SIDE OF HOUSE, LOOKING BACK TOWARDS DOOR TO MAIN BASEMENT AREA. ORIGINAL SINK IN PHOTO CENTER BELOW THIRD 1-LIGHT, SIDE-HINGED WINDOW ON NORTH WALL. VIEW TO WEST.
- CA-145-1-C-13 INTERIOR OF FRONT ENCLOSED PORCH SHOWING ENTRANCE DOOR. VIEW TO SOUTH.
- CA-145-1-C-14 INTERIOR OF FRONT ENCLOSED PORCH, OPPOSITE VIEW OF CA-145-1-C-13. FRONT ENTRANCE DOOR TO HOUSE IS VISIBLE AT LEFT PHOTO CENTER. VIEW TO NORTH.
- CA-145-1-C-15 INTERIOR DETAIL OF FRONT PORCH SUPPORT. VIEW TO SOUTHWEST.

BISHOP CREEK HYDROELECTRIC SYSTEM,
CONTROL STATION,
WORKER COTTAGE (BUILDING 103)
HAER No. CA-145-1-C
INDEX TO PHOTOGRAPHS (Page 3)

- CA-145-1-C-16 COMBINED LIVING/DINING ROOM INTERIOR SHOWING FRONT DOOR ENTRY AND DOOR TO FRONT BEDROOM AT PHOTO LEFT. REMAINS OF ORIGINAL PARTITION WALL IS VISIBLE AT CENTER OF ROOM. VIEW TO WEST.
- CA-145-1-C-17 COMBINED LIVING/DINING ROOM INTERIOR, KITCHEN IN BACKGROUND. BRICK PEDESTAL FOR WOOD-BURNING HEATER AND DOORWAY TO BACK BEDROOM AT PHOTO RIGHT. VIEW TO EAST.
- CA-145-1-C-18 KITCHEN INTERIOR, LIVING/DINING ROOM IN BACKGROUND. VIEW TO WEST.
- CA-145-1-C-19 KITCHEN INTERIOR SHOWING BUILT-IN CABINETRY AROUND SINK. VIEW TO SOUTHWEST.
- CA-145-1-C-20 KITCHEN INTERIOR SHOWING SMALL ADJACENT UTILITY ROOM. VIEW TO NORTHEAST.
- CA-145-1-C-21 UTILITY ROOM INTERIOR SHOWING SOUTH SIDE OUTSIDE ENTRANCE TO KITCHEN. VIEW TO SOUTH.
- CA-145-1-C-22 REAR ENCLOSED PORCH INTERIOR SHOWING OPEN DOOR TO UTILITY ROOM AND CLOSED DOOR TO BACK BEDROOM. VIEW TO SOUTHWEST.
- CA-145-1-C-23 REAR ENCLOSED PORCH INTERIOR, OPPOSITE VIEW FROM CA-145-1-C-22. VIEW TO NORTHWEST.
- CA-145-1-C-24 FRONT BEDROOM INTERIOR LOOKING THROUGH DOOR TO LIVING/DINING ROOM. OPEN CLOSET DOOR IS A PHOTO RIGHT. VIEW TO SOUTH.
- CA-145-1-C-25 FRONT BEDROOM CLOSET INTERIOR SHOWING ATTIC CRAWLSPACE DOOR IN CEILING. VIEW TO NORTHWEST.
- CA-145-1-C-26 FRONT BEDROOM INTERIOR SHOWING ORIGINAL 1 LIGHT OVER 1 LIGHT WINDOWS. VIEW TO NORTHEAST.

BISHOP CREEK HYDROELECTRIC SYSTEM,
CONTROL STATION,
WORKER COTTAGE (BUILDING 103)
HAER No. CA-145-1-C
INDEX TO PHOTOGRAPHS (Page 4)

- CA-145-1-C-27 FRONT BEDROOM INTERIOR LOOKING THROUGH
BATHROOM. OPEN CLOSET DOOR IS VISIBLE AT PHOTO
LEFT. VIEW TO WEST.
- CA-145-1-C-28 BATHROOM INTERIOR LOOKING THROUGH DOOR INTO
FRONT BEDROOM. TILE SHOWER STALL AT PHOTO RIGHT,
SINK AT PHOTO LEFT. VIEW TO EAST.
- CA-145-1-C-29 BATHROOM DETAIL SHOWING BATHTUB. OPEN DOOR TO
BACK BEDROOM AT PHOTO LEFT. VIEW TO WEST.
- CA-145-1-C-30 BATHROOM DETAIL SHOWING, BUILT-IN CABINET, TOILET,
AND OPEN DOOR TO BACK BEDROOM. VIEW TO
SOUTHWEST.
- CA-145-1-C-31 BACK BEDROOM INTERIOR LOOKING THROUGH OPEN DOORS
TO BATHROOM ON PHOTO LEFT, CLOSET IN PHOTO CENTER
AND COMBINED LIVING/DINING ROOM AT PHOTO RIGHT.
VIEW TO SOUTHEAST.